



Safety Notice

Be aware of hand trap points on davits

This picture shows the trap points on a davit on one of our sites. An operative injured his finger when it became trapped between the davit arm and the main post, as shown.

Actions to be taken:

- Inspect all davits on your site for similar trap points
- Put davits with similar problems out of use until remedial measures can be put into place
- Notify Jill Martin in Redhill of any davits that require alteration

Any queries then contact your local safety adviser.

